Florida House of Representatives - 2001 HB 1709 By the Fiscal Responsibility Council and Representative Dockery

I	
1	A bill to be entitled
2	An act relating to boiler safety; repealing s.
3	554.106, F.S., which requires the Department of
4	Insurance to employ deputy inspectors under ch.
5	554, F.S., the Boiler Safety Act; amending s.
6	554.105, F.S., to conform; amending s. 554.108,
7	F.S., to conform; providing that each
8	inspection of a boiler under the Boiler Safety
9	Act shall be conducted by a special inspector;
10	amending s. 554.111, F.S.; eliminating
11	certificate inspections and other specified
12	inspections conducted by the department and
13	fees therefor; providing an effective date.
14	
15	Be It Enacted by the Legislature of the State of Florida:
16	
17	Section 1. Section 554.106, Florida Statutes, is
18	repealed.
19	Section 2. Paragraph (d) of subsection (2) of section
20	554.105, Florida Statutes, is amended to read:
21	554.105 Chief inspector
22	(2) The department, through the chief inspector, shall
23	administer the state boiler inspection program, and shall:
24	(d) Expend funds necessary to meet the expenses
25	authorized by ss. 554.1011-554.115, including the necessary
26	travel expenses of the chief inspector and deputy inspectors,
27	and the expenses incident to the maintenance of his or her
28	office.
29	Section 3. Subsections (2) , (4) , and (5) of section
30	554.108, Florida Statutes, are amended to read:
31	554.108 Inspection
	1

CODING:Words stricken are deletions; words <u>underlined</u> are additions.

Florida House of Representatives - 2001 187-899-01

1 Each inspection of a boiler conducted pursuant to (2) 2 ss. 554.1011-554.115 shall be made by the chief inspector, a 3 deputy inspector, or a special inspector. 4 (4) Deputy inspectors and Special inspectors shall 5 file a written report on each certificate inspection with the 6 chief inspector within 15 days following such inspection. The 7 filing of reports of inspections other than certificate 8 inspections are not required unless such inspections disclose that a boiler is in an unsafe condition. 9 10 (5) Upon determining that a boiler is in an unsafe 11 condition and poses an imminent danger to the public health, 12 safety, and welfare, the chief inspector, a deputy inspector, 13 or a special inspector may immediately order the boiler to be 14 shut down. The boiler shall remain shut down until a reinspection by a certified inspector determines that all 15 violations have been corrected, that the boiler may be 16 operated safely, and that a certificate of compliance has been 17 issued. 18 19 Section 4. Section 554.111, Florida Statutes, is 20 amended to read: 21 554.111 Fees.--22 (1) The department shall charge the following fees: For an applicant for a certificate of competency, 23 (a) 24 the initial application fee shall be \$50, and the annual renewal fee shall be \$30. The fee for examination shall be 25 26 \$50. 27 (b) For certificate inspections conducted by the 28 department: 29 1. For power boilers and high pressure, high temperature water boilers of: 30 31 4,000 square feet or less 2

CODING: Words stricken are deletions; words underlined are additions.

Florida House of Representatives - 2001 187-899-01

1 2 3

4 5

6 7 8

9

10

11 12

13 14

15

17

19

22 23

25

26

27

29

30

heating surface.....\$60 More than 4,000 square feet heating surface and less than 10,000 square feet of heating surface.....\$70 10,000 square feet or more heating surface......\$90 2. For heating boilers: Without a manhole.....\$40 3. For hot water supply boilers.....\$40 (b)(c) For issuance of a compliance certificate without a 16 department inspection.....\$30 (c)(d) Duplicate certificates or 18 address changes.....\$5 (2) Not more than an amount equal to one certificate inspection fee shall be charged or collected for any and all 20 boiler inspections in any inspection period, except as 21 otherwise provided in ss. 554.1011-554.115. (a) When it is necessary to make a special trip to 24 observe the application of a hydrostatic test, an additional fee equal to the fee for a certificate inspection of the boiler shall be charged. (b) All other inspections, including shop inspections, 28 surveys, and inspections of secondhand boilers made by the chief inspector or a deputy inspector, shall be charged at the rate of not less than \$270 for one-half day of 4 hours, and 31

CODING: Words stricken are deletions; words underlined are additions.

Florida House of Representatives - 2001 187-899-01

\$500 for 1 full day of 8 hours, plus travel, hotel, and incidental expenses in accordance with chapter 112. The chief inspector shall deposit all fees (3) received pursuant to ss. 554.1011-554.115 into the Insurance Commissioner's Regulatory Trust Fund. Section 5. This act shall take effect July 1, 2001. б HOUSE SUMMARY Repeals provisions which require the Department of Insurance to employ deputy inspectors under ch. 554, F.S., the Boiler Safety Act, and conforms provisions accordingly. Provides that each inspection of a boiler under the Boiler Safety Act shall be conducted by a special inspector. Eliminates certificate inspections and other specified inspections conducted by the department and fees therefor and fees therefor.

CODING: Words stricken are deletions; words underlined are additions.